

October 20, 2025

RE: Follow up on 0.2µm filter supply shortage

Dear Valued Customer,

As mentioned in our prior customer communication (BD-152114) on June 23, 2025, we continue to face a supplier-related shortage of large volume 0.2µm filters, which is impacting BD Alaris™ Pump Sets and BD Gravity and Extension Sets (see Appendix 1 for list of affected products). While we are doing our utmost to continue supplying large volume 0.2µm filter tubing, we are unable to meet full allocation needs at this time. Based on projection of incoming raw material, BD expects to produce the affected 0.2µm BD Alaris™ Pump Sets at roughly 90% of historical volume and the affected 0.2µm BD Gravity and Extension Sets at roughly 60% of historical volume. To manage this situation effectively and help meet all customers' demand, BD has taken the following actions:

- Prioritized production of specific product catalog numbers based on vendor allocations to maximize production output; thus, some
  product catalog numbers will not be available in the short term and open orders for temporarily postponed products will be cancelled.
  (see Appendix 2).
- Implemented allocation reviews to manage direct orders and prevent stockpiling.
- In order to correctly prioritize current demand, we will also cancel any direct orders on products that have aged more than 30 days on all products in this notification. If you have an order that is cancelled as a result, we ask that you evaluate your inventory position and re-submit an order only for the amount of product needed to continue care vs order to stock.

## For further information:

Please contact your local BD sales associate or BD Customer Care at 1-844-823-5433 or visit www.bd.com/en-us/support. Thank you for your continued patronage and support.

David Rodriguez Molina

Associate Director, Infusion Delivery Solutions

WW Infusion Preparation and Delivery

BD Switzerland Sarl Route de Crassier 17 1262 Eysins, Switzerland bd.com

## Appendix 1: Affected Products & Estimated Backorder Recovery Timelines


**Estimated Backorder Recovery:** All orders covered on-time and in full based on historical demand. This does not indicate that product will be removed from allocation.

Catalog Number	Product Description	Estimated Backorder Recovery Date
10010454	AS LVP 20D LOW SORB SS 0.2M	Temporarily De-Prioritized
2434-0007	AS LVP 20D SS 0.2M CV	Temporarily De-Prioritized
11532269	AS LVP 20D LOW SORB 2SS 0.2M CV	March 2026 (remains on allocation)
10015012	AS LVP BUR 20D LOW SORB SMBORE SS 0.2M	Temporarily De-Prioritized
2432-0007	AS LVP 20D 3SS 0.2M CV	March 2026
24301-0007T	AS LVP SS BAG 20D LOW SORB SS TEX 0.2M	Temporarily De-Prioritized
2465-0007	AS LVP SS BAG 20D LOW SORB SS 0.2M	March 2026
20350E	EXT LOW SORB SPS 0.2MF DEHP FREE	March 2026
20027E	EXT SET 0.2 MICRON FILTER SS DEHP FREE	March 2026
42933E	GRAV SET 105" 20DRP V/NV BCV 2NFC-SS .2MIC FLTR ROLL CLMP 2-PIECE LL	Temporarily De-Prioritized
20350ET	EXTENSION SET W/.2MF, SMARTSITE & TEXIUM	Temporarily De-Prioritized
10013902	EXTENSION SET LOW SORB W/.2MF, SMARTSITE	Temporarily De-Prioritized

## **Appendix 2: Prioritized Production**

\*Items below are prioritized sequentially, starting with the highest priority at the top

Prioritized Catalog Number	Temporarily Postponed Catalog Number	Prioritized Catalog Number Differences
11532269	10010454	-Has a back check valve
[20]		-Has one additional SmartSite Y-Site
		-10 in. longer
		-Has 3mL higher priming volume
2432-0007	2434-0007	-Has 2 additional SmartSite Y-Sites.
		-Has 1mL higher priming volume
20350E	4030B-07T	-Extension set rather than a secondary set
		-Does not come with priming cap with hanger
		-Has 1 SmartSite Y-Site
		-Does not contain DEHP in its material formulation
		-5 in. shorter
		-Has 6mL lower priming volume



BD-152114

BD Switzerland Sarl Route de Crassier 17 1262 Eysins, Switzerland bd.com

2465-0007 N/A N/A