

September 2025

Dear valued BD customer,


This letter provides an update on the impending launch and availability of the BD Veritor™ System for SARS-CoV-2 which recently received FDA 510(k) clearance. This letter also details specifics on the BD Veritor™ Analyzer firmware required and ordering guidance.

To better support COVID testing needs due to the increased COVID prevalence nationally over the summer months, and to facilitate any validation studies ahead of the upcoming respiratory season, BD is pleased to announce that we anticipate the BD Veritor™ System for SARS-CoV-2 assay (Cat. No. 256092) to be available for purchase beginning in mid-September 2025.

The existing EUA-authorized BD Veritor™ System for Rapid Detection of SARS-CoV-2 (Cat. No. 256082) will continue to remain available for purchase and use until the current inventory is exhausted.

BD has ceased production of the EUA-authorized BD Veritor™ System for Rapid Detection of SARS-CoV-2 per FDA guidance and has converted production to the BD Veritor™ System for SARS-CoV-2 510(k).

Customers are advised that only BD Veritor™ Analyzers with firmware v6.01 and above can process the BD Veritor™ System for SARS-CoV-2 510(k) cleared assay. To determine the firmware, simply press the blue power button and review the firmware displayed on the screen (example image below).



If the firmware displayed on the screen is not v 6.01, please contact your BD or distributor sales representative who will be able to assist in obtaining a replacement BD Veritor™ Analyzer.

For more information or support, customers can contact BD Customer Service at 800-638-8663.

Regards,

BD POC Marketing Team