



December 16, 2025

Subject: Repeater Pump Fluid Transfer Set Allocation and Packaging Update

Dear Valued Customer,

Baxter is committed to providing transparent updates regarding supply and product enhancements, so you may plan your patient care with confidence. We would like to inform you of important updates related to Baxter Repeater Pump Fluid Transfer Sets.

Allocation Update

We have made enhancements to strengthen our supply chain resiliency that have improved product availability. Due to these improvements, allocation has increased from 50% to 75% for Product Code H93811, effective **January 1, 2026**. Please see Table 1 for more details.

Allocation will remain at 50% for the remaining Repeater Pump Fluid Transfer Set Product Codes listed in Table 1. Allocation levels will be continually reviewed based on supply and demand projections, and additional adjustments will be made accordingly and communicated proactively.

Table 1: Product Codes, Allocation Level, Estimated Availability Date

Product Code	Product Description	Allocation as of 1/1/26	Estimated Product Availability
H93811	REPEATER PUMP TUBE SET VENTED	75%	Q1 2026
H93821	REPEATER PUMP TUBE SETMALE LUER LOCK OUTLET	50%	Q3 2026
H938331	REPEATER PUMP TUBE SETMICRO VOLUME LOW PRIME	50%	Q3 2026
H93862	REPEATER PUMP TUBE SETBIFURCATED	50%	Q3 2026
H93813	REPEATER PUMP TUBE SETORAL NON STERILE	50%	Q3 2026
H93863	REPEATER PUMP TUBE SETTRIFURCATED	50%	Q3 2026
H9389BTS	REPEATER PUMP TUBE SETORAL STANDARD VOLUME EUCLID	50%	Q3 2026

Product Enhancements

As a part of our continuous improvement efforts, Baxter has implemented enhancement to the packaging and colorant of the Repeater Pump Fluid Transfer Sets.

Paper bands around the tubing have been added to improve product organization and protect components during transit. Paper bands are to be removed prior to use. This enhancement does not affect product performance, sterility, or compatibility.

Baxter has also reduced the colorant concentration in the blue connectors used in the Repeater Pump Tubing Sets by 3%. This change does not impact product performance, sterility, or compatibility.

We recognize the importance of consistent and reliable supply and remain committed to communicating these product changes as a valued partner. Your Baxter sales representative is available to assist with questions regarding these updates, or you can contact Center for Service at 1-888-229-0001.

Thank you for being a valued Baxter customer.

Caroline Gullion
Director, U.S. Marketing,
IV Fluids & Pharmacy Solutions
Baxter International, Inc.