



Technical Bulletin

Date: March 12, 2026

To: Applicable Internal Departments + Distribution Partner

From: Mark Hoying, Manager, Senior Post Sales Support

Topic: Medical—Parts Discontinuation Notice

At Midmark, we take pride in providing our customers with quality products and services that can be relied upon to improve efficiency and patient care while ensuring integrity, performance and safety. For these reasons, Midmark has made the decision to end the product service for several models that have been out of production for more than ten (10) years. Acquiring parts for these older models from Midmark authorized suppliers has become limited, leaving us unable to effectively service the products and best serve our customers.

Effective immediately, parts and service for the product models listed here are no longer available from Midmark. The affected End of Service models include the following:

- 265-001, 265-002, 265-003, 665-001, 665 002, 665-003 Procedure Carts
- 667-001 Diagnostic Cart
- 4-000-0026, 1-100-1225/1226 Midmark IQspiro Digital Spirometer (USB) w/ syringe (55 Series)
- 4-000-0025, 1-100-1225/1226 Midmark IQspiro Digital Spirometer (USB) (55 Series)
- 4-000-0110 Midmark IQholter with one Recorder
- 4-000-0113 Midmark IQholter EX with one Recorder
- 4-000-0116 Midmark IQholter EP with Pacemaker detection and one Recorder
- 4-000-0119, 1-370-0005, 1-370-0007, 1-370-0006 Midmark IQholter Recorder

For questions, please contact Medical Technical Support at 1.844.856.1230.

Designing better care.®

Mark Hoying
Manager, Senior Post Sales Support
Midmark Corporation

| |
|----------------------------------|
| 077-22259-00 Rev A1 ECO125581 |
|----------------------------------|