

November 2025

Subject: 3M™ Bair Hugger™ Underbody Warming Blankets Catalog Code Changes

Dear Distributor,

Solventum is introducing updated designs of the Bair Hugger™ underbody warming blankets to **increase production capacity** and **improve service levels**. Production of the new blankets began in November 2025, with changes - including a **new catalog code** - expected to take effect in mid-December 2025.

The new blankets are compatible with existing Bair Hugger™ warming units and should not impact your clinical practice.

Please load the following redesigned catalog numbers in your system but refrain from activating them until we provide confirmation that they are live.

Phase-Out Product		Phase-In Product	
Catalog Number	Product Description	Redesigned Catalog Number	Product Description
55501	3M™ Bair Hugger™ Warming Blanket 55501, Pediatric Underbody, 10/Case	55502	Bair Hugger™ Warming Blanket 55502, Pediatric Underbody, 10/Case
45534	3M™ Bair Hugger™ Warming Blanket, 45534 NOVAPLUS Pediatric Underbody, 10/Case	55502	Bair Hugger™ Warming Blanket 55502, Pediatric Underbody, 10/Case *NovaPlus Approved*
55000	3M™ Bair Hugger™ Warming Blanket 55000, Large Pediatric Underbody, 10/Case	55001	Bair Hugger™ Warming Blanket 55001, Large Pediatric Underbody, 10/Case
45034	3M™ Bair Hugger™ Warming Blanket 45034, NOVAPLUS Large Pediatric Underbody, 10/Case	55001	Bair Hugger™ Warming Blanket 55001, Large Pediatric Underbody, 10/Case. *NovaPlus Approved*
63500	3M™ Bair Hugger™ Warming Blanket 63500, Full Access Underbody, 5/Case	63501	Bair Hugger™ Warming Blanket 63501, Full Access Underbody, 5/Case
57501	3M™ Bair Hugger™ Warming Blanket 57501, Spinal Underbody, 5/Case	57502	Bair Hugger™ Warming Blanket 57502, Spinal Underbody, 5/Case
54500	3M™ Bair Hugger™ Warming Blanket 54500, Adult Underbody, 10/Case	54501	Bair Hugger™ Warming Blanket 54501, Adult Underbody, 10/Case
58501	3M™ Bair Hugger™ Warming Blanket 58501, Lithotomy Underbody, 10/Case	58502	Bair Hugger™ Warming Blanket 58502, Lithotomy Underbody, 10/Case

Key differences to note:

- In an effort to reduce medical waste, the tuck flaps have been removed from the 635, 585 and 555 blankets and replaced with optional adhesive strips
- The hose card used to attach the warming unit is now cardboard instead of plastic and are located on the top of the blankets instead of the sides

If you have any questions about this change, please contact your Solventum Account Manager. Thank you for allowing us to serve you now and in the future.

Regards,

Caitlin A. Bissell



Sr Portfolio Manager, IP+SS